



- +3VA_EC 38.47
- +3VS 14.1, 20.21, 22, 23, 25, 26, 27, 28, 30, 37, 38, 39, 40, 41, 43, 47, 48, 49, 53, 55, 60, 63, 65, 66, 91, 92
- +3VSB 4.22, 23, 27, 28, 30, 43, 61, 81, 92
- +3VA 20.27, 60, 63, 65, 66, 91, 92

R1.2 2012/11/08
cost down 0ohm


R1.2 2012/11/06
工廠要求增加

R1.2 2012/11/08
cost down 0ohm
R1.2 2012/11/28
change to 33ohm for Intel check list
R1.2 2012/12/07
R3056~R3059 are replaced by SP3014, SP3015, SP3019, SP3020
R1.2 2012/12/17
SP3014, SP3015, SP3019, SP3020 are replaced by 0ohm

R1.2 2012/11/06
工廠要求增加

R1.2 2012/11/08
cost down 0ohm
R1.2 2012/11/28
change back to 0ohm
R1.2 2012/11/06
R3042, R3044 are replaced by SP3008, SP3012
R1.2 2012/11/17
SP3008, SP3012 replaced by 0ohm

Share ROM



non-Share ROM

